

MONITOR FUNCTIONS

Knob	Screen brightness
Backlight	Guides
Chroma	HLG
3D LUT	Sharpness
Contrast	Vector Scope
Tint	RGB Histogram
Grids	RGB Waveform
Zebra	Luma Histogram
H Flip	Luma Waveform
V Flip	Audio Meters
Cross Hair	Rectangle Crop
Anamorphic	4 custom shortcut keys
Osd Flip Mode	SDI Load LUT Output
Peaking Focus	SDI output from P turn to I
ARRI False Color	3G SDI Level A/B AUTO Output
13 Colors of False Color	HDMI / SDI Conversion
Preset Color Temperature	HDMI 1080P60 simul screen output
Manual Setting Color Temperature	Red, green, blue, white, and solid color

PARTIAL FUNCTION DISPLAY



Peaking Focus



False Color



Zebra



All-waveform(LUM/RGB/VEC Waveform、LUM/RGB Histogram)、Stereo Audio Meters



3D LUT Before Opening



3D LUT After Opening